From: Miller, Garyg
To: David Keith

Subject: RE: San Jacinto Update

Date: Thursday, March 24, 2016 9:14:00 AM

Great – thanks David

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov

From: David Keith [mailto:dkeith@anchorgea.com]

Sent: Thursday, March 24, 2016 9:13 AM **To:** Miller, Garyg < Miller. Garyg@epa.gov>

Cc: Sanchez, Carlos <sanchez.carlos@epa.gov>; Dave Moreira (dmoreira@wm.com)

<dmoreira@wm.com>; Phil Slowiak <philip.slowiak@ipaper.com>

Subject: RE: San Jacinto Update

Gary — They should finish installing the camera system today and all maintenance activities described in the work plan we submitted earlier this week are complete. Two additional small (1x1 to 1x2 foot) locations were identified in the final probing on Tuesday, and those will also be addressed with more rock added today. Valmichael approved addressing the final two maintenance areas while he was on site.

Please let me know if you need anything else. The attached is the daily report for Tuesday's activities and I should have yesterday's report to you later today.

Thanks, David

From: Miller, Garyg [mailto:Miller.Garyg@epa.gov]

Sent: Thursday, March 24, 2016 7:58 AM **To:** David Keith < dkeith@anchorqea.com **Cc:** Sanchez, Carlos < sanchez.carlos@epa.gov

Subject: San Jacinto Update

David,

Can you send a brief summary of the work completed at the site this week? Would appreciate it this morning se we can let the folks here know the progress.

Thanks,



Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov